



SERVICE BULLETIN

Health Imaging Products

Eastman Kodak Company, Health Imaging, Rochester, NY 14650

SERVICE BULLETIN NO. 289

Revised September 2001

Supersedes August 1999

3425 Kodak X-Omat 5000RA PROCESSOR
3228 Kodak X-Omat 480RA PROCESSOR
3056 Kodak X-Omat 460RA PROCESSOR
3040 Kodak RP X-Omat PROCESSOR, MODEL M6B

Dryer Drive Belt Information

| Part Number | Model(s) | Inside Circumference | Thickness |
|-------------|--|--|-------------------------|
| 968433 | <ul style="list-style-type: none">480RA <u>without</u> TURNAROUND ENHANCEMENT KIT.M6B and M6I <u>with</u> top BELT TENSIONER (current production) | 143.51 cm +/- 0.635 cm (56.50 in. +/- 0.250 in.) | 0.762 mm (0.030 in.) |
| 651125 | <ul style="list-style-type: none">460RAM6B and M6I <u>with</u> bottom BELT TENSIONER (old configuration) *M6AN and M6AW* <p>* SPM subs p/n 462452 & 261284 to p/n 651125</p> | 143.51 cm +/- 0.635 cm (56.500 in. +/- 0.250 in.) | 1.727 mm (0.068 in.) |
| 8B7344 | 480RA <u>with</u> TURNAROUND ENHANCEMENT KIT. | 141.61 cm +/- 0.318 cm (55.750 in. +/- 0.125 in.) | 0.762 mm (0.030 in.) |
| 5B6350 | 5000RA | 140.97 cm +/- 0.318 cm (55.500 in. +/- 0.125 in.) | 0.762 mm (0.030 in.) |

Deb Trubatch, Service Engineer- Rochester

For More Information:

U.S. Distributors Contact:

**Health Imaging
Customer Support Operations
1-800-336-4722**

GCSS Personnel Contact:

**Film Handling TAC
U.S.: 1-800-822-1414
Canada: 1-800-433-1414
International: 716-724-4675**

Kodak and X-Omat are trademarks.

Pub No. 3E1785

